CENTRAL INTELLIGENCE AGENCY

INFORM	NATION R	EPORT	amended. Its transmission or revelation of its contents to or receipt by an unauthorised person is prohibited by law. The reproduction of this form is prohibited.			
			L - U.S. OFFICIALS	ONLY		25X1
COUNTRY	Poland			REPORT		
SUBJECT	Streeto	ar and Trolley	Bus Breakdowns in	DATE DISTR.	18 June 1	953
	Warsaw		•	NO. OF PAGES	2	
DATE OF IN	160	<u>a sassifia</u>		REQUIREMENT NO.	RD	-
				REFERENCES	*	25X1
PLACE ACQ	JIRED	<u> </u>		REFERENCES		
		This is	UNEVALUATED Info	ormation		
			UATIONS IN THIS REPORT A AISAL OF CONTENT IS TENT (FOR KEY SEE REVERSE)			25X1
	power static presence of Several eng:	on in the Groché water in the ma ineers working i	bruary 1953, three of the burnt	out owing to the	alleged pr	
5	streetoar se	of these turbing arvices. In the le in the depot, from that distr	nes resulted in a so Grochów district and instead of the rict, there was onl	about 100 street ne usual four min	cars were ute street-	
4.	in the morn	ings. Since lace as a legitimate ork overtime to ritation among t	wn, hundreds of peak of, or breakdown ce excuse for tardinake up. This nather people thus for	n in, transport i iness, these peop turally caused ac	s not accepted le were all ute annoy-	
5.	packed with	arly in February	also affected, but y, seven and five served standing stan	trolley buses re	On two spectively, le to	
• • • [Сош	ments:				25 X 1
25 YEAR F	It is taking cars s	doubtful if more the road at pro- tanding idle in and are not ne- in the power st	ars said to be idle than 150 streets esent. It is cons. Grochew and other cessarily kept off ation. The motor	ars in Warsaw are idered that many depots are in no the roads merely bus services are	of the street- ed of mechanic owing to brea	97
			NTROL - U.S. OFFIC	IALS ONLY	 	7
STATE	x ARMY x	NAVY X AIR	X FBI	100		d S

SECRET/CONTROL =	U.S.	OFFICIALS	ONLY		
------------------	------	-----------	------	--	--

-2-

parlous state than the streetcars. Scarcity of spare parts (especially springs, which are constantly breaking through overloading) and tires is creating havon in the motor bus services.

2. The twolley buses are in much better shape at present although they suffer unnecessary damage to motors and booms due to the inexpert driving of these vehicles.

SECRET/CONTROL & U.S. OFFICIALS ONLY

25X1